

**EI1252- TRANSDUCER ENGINEERING**  
**TWO MARKS Q & A**  
**UNIT 1**

1) What is instrument?

It is a device for determining the value or magnitude of a quantity or variable.

2) Add  $826 \pm 5$  to  $628 \pm 3$ .

$$N1 = 826 \pm 5 \text{ (} = \pm 0.605\% \text{)}$$

$$N2 = 628 \pm 3 \text{ (} = \pm 0.477\% \text{)}$$

$$\text{Sum} = 1,454 \pm 8 \text{ (} = \pm 0.55\% \text{)}$$

3) Subtract  $628 \pm 3$  from  $826 \pm 5$ .

$$N1 = 826 \pm 5 \text{ (} = \pm 0.605\% \text{)}$$

$$N2 = 628 \pm 3 \text{ (} = \pm 0.477\% \text{)}$$

$$\text{Difference} = 198 \pm 8 \text{ (} = \pm 4.04\% \text{)}$$

4) List three sources of possible errors in instruments.

Gross Error, Systematic & Random errors.

5) Define Instrumental error

These are the errors inherent in measuring instrument because of their mechanical structure.

6) Define limiting error

Components are guaranteed to be within a certain percentage of rated value. Thus the manufacturer has to specify the deviations from the nominal value of a particular quantity.

7) Define probable error

It is defined as  $r = \pm 0.6745\sigma$  where  $\sigma$  is standard deviation.

Probable error has been used in experimental work to some extent in past, but standard deviation is more convenient in statistical work.

8) Define Environmental error

These are due to conditions in the measuring device, including conditions in the area surrounding the instrument, such as the effects of changes in temperature, humidity.

9) Define arithmetic mean.

The best approximation method will be made when the number of readings would give the best result,

$$X = \frac{x_1 + x_2 + x_3 + \dots + x_n}{n} = \frac{\sum x}{n}$$

X = arithmetic mean;

$x_1, x_2, x_n$  = readings taken

n = number of readings.

10) Define average deviation.

$$D = \frac{|d1| + |d2| + |d3| + \dots + |dn|}{n} = \frac{\sum |d|}{n}$$

By definition, average deviation is the sum of absolute values of the value deviations divided by the number of reading.


11) Define units.

It is necessary to define a physical quantity both in kind and magnitude in order to use this information for further proceedings. The standard measure of each kind of physical quantity is named as the unit.

12) Define Standards

The physical embodiment of a unit of measurement is a standard. For example, the fundamental unit of mass in the international system is the kilogram and defined as the mass of a cubic decimeter of water at its temperature of maximum density of 4°C.

13) Draw the functional block diagram of a measurement system.



14) Mention the purpose of the measurement.

- To understand an event or an operation.
- To monitor an event or an operation.
- To control an event or an operation.
- To collect data for future analysis
- To validate an engineer design.

15) What are the methods of measurement?

- Direct comparison method
- Indirect comparison method

16) Define ODDs

The specification of limiting error is in itself uncertain because the manufacture himself is not sure about the accuracy because of the presence of random errors.

17) Classify Standards.

- International standards
- Primary standards
- Secondary standards
- Working standards

18) Define transducer and give an example.

Transducer is a device which convert one form of energy into electrical energy. A thermocouple converts heat energy into electrical voltage.

19) Classify- transducer.

- On the basis of transduction form used
- As primary and secondary transducers
- As active and passive transducers
- As analog and digital transducers.
- As transducers and inverse transducers

20) What is primary transducer?

Bourdon tube acting as a primary transducer, senses the pressure and convert the pressure into displacement. No output is given to the input of the bourdon tube. So it is called primary transducer. Mechanical device can act as a primary transducer.

21) What is secondary transducer?

The output of the Bourdon tube is given to the input of the LVDT. There are two stages of trasduction, firstly the pressure is converted into a displacement by the Bourdon tube then the displacement is converted into analog voltage by LVDT. Here LVDT is called secondary transducer. Electrical device can act as a secondary transducer.

22) What is passive transducer?

In the absence of external power, transducer cannot work and it is called a passive transducer. Example capacitive , inductive, resistance transducers.

23) What is active transducer?

In the absence of external power, transducer can work and it is called active transducer. Example velocity, temperature, light can be transduced with the help of active transducer.

24) What is analog transducer?

These transducers convert the input quantity into an analog output which is a continuous function of time. Thus a strain gauge, an LVDT, a thermocouple or a thermistors may be called analog transducer, as they give an output which is a continuous function of time.

25) Give the classification of units.

1. Absolute units
2. Fundamental and derived units
3. Electromagnetic units
4. Electrostatic units

26. Define Primary fundamental and auxiliary fundamental units.

Fundamental units in mechanics are measures of length, mass and time and those are fundamental to most other physical quantities and hence they are called Primary fundamental units

Measures of certain physical quantities in thermal, electrical and illumination fields are also represented by fundamental units and are used only where those disciplines are involved and hence called auxiliary fundamental units.

27. Define the unit of mass preserved at International Bureau of weights and measures at Sevres, Near Paris.

The unit of mass is represented by a material standard; the mass of International prototype kilogramme consisting of platinum Iridium hollow cylinder.

28. Define static calibration.

It refers to a process in which all the inputs (desired, modifying, interfering) except one are kept at some constant values.

29. Define Traceability.

The ability to trace the accuracy of the standard back to its ultimate source in fundamental standards of National Institute of Science and Technology is termed "Traceability"

30. What are random errors or residual errors.

The happenings or disturbances about which we are unaware and lumped together are called random errors or residual errors. Since these errors remain even after the systematic errors are taken care of, they are called residual errors.

31. Give one property of piezo-electric crystal.

When a force is applied to piezo-electric crystals, they produce an output voltage.

32. Define an Inverse transducer. Give an example.

A device which converts an electrical quantity into a non-electrical quantity. A piezo-electric crystal acts as an inverse transducer because when a voltage is applied across its surfaces, it changes its dimensions causing a mechanical displacement.

33. List the factors responsible in selection of a transducer.

1. Operating principle
2. Sensitivity
3. Operating range.
4. Accuracy.

## UNIT 2

20) Define static characteristics.

static characteristics of a measurement system are, in general, those that must be considered when the system or instrument is used to measure a condition not varying with time.

21) Mention different types of static characteristics.

(i) accuracy (ii) sensitivity (iii) Reproducibility (iv) Drift (v) Static error and (vi) Dead zone .

22) What is dynamic characteristics?

Many measurements are concerned with rapidly varying quantities and , therefore, for such cases we must examine the dynamic relations which exist between the output and the input . This is normally done with the help of differential equations . Performance criteria based upon dynamic relations constitute the Dynamic Characteristics.

23) Mention different types dynamic characteristics?

- Zero- order transducers
- First - order transducers
- Second-order transducers
- Higher-order transducers

24) What are the test inputs of the transducer?

- Impulse input
- Step input
- Ramp input
- Parabolic input
- Sinusoidal input

25) Define- zero order transducer.

The input- output relationship of a zero- order transducer is given by

$$Y(t) = K r(t)$$

Where  $r(t)$  is the input,  $Y(t)$  is the output and  $K$  is the static – sensitivity of the transducer. Example for zero- order transducer is a potentiometer.

26) What is mathematical model?

27) What is frequency response of ZOT.

Frequency response is thus defined as the steady – state output of a transducer When it is excited with sinusoidal input . the frequency response is represented with the help of two plots namely amplitude ratio verses frequency and phase angle shift versus frequency.

28) What is damping ratio?

The damping ratio  $\zeta$  is an important parameter which decides the nature of oscillation in the transducer output . when  $\zeta = 0$  , the second – order system is said to be un damped and the system behaves like an oscillator . when  $\zeta = 1$  , the second – order system is said to be critical damped and when  $\zeta > 1$  , the second – order system is said to be over damped.

29) Define static sensitivity

Sensitivity should be taken depending on the operating point. The sensitivity is expressed in output unit/ input unit.

30) Define linearity.

Linearity is a measure of the maximum deviation of the plotted transducer response from a specified straight line .

31) Compare accuracy and precision.

Accuracy is the closeness to true value whereas precision is the closeness amongst the readings .precision is the degree of closeness with which a given value may be repeatedly measured.

32) What is Threshold?

When the input to a transducer is increased from zero, there is a minimum value below which no output can be detected .This minimum value of the input is defined as the threshold of the transducer.

33) Define resolution.

When the input to a transducer is increased slowly from some non-zero arbitrary value, the change in output is not detected at all until a certain input increment is exceeded. This increment is defined as the resolution.

34) Define hysteresis.

When the input to a transducer which is initially at rest is increased from zero to full-scale and then decreased back to zero, there may be two output values for the same input. Hysteresis effects can be minimized by taking readings corresponding to ascending and descending values of the input and then taking their arithmetic average.

35) What is range and span?

The range of the transducer is specified as from the lower value of input to higher value of input.

The span of the transducer is specified as the difference between the higher and lower limits of recommended input values.

36) What is rise time ?

It is defined as time required for the system to rise from 0 to 100 per cent of its final value .

37) A thermometer has a time constant of 3.5 s. it is quickly taken from a temperature 0degree c to a water bath having temperature 100degree c. what temperature will be indicated after 1.5 s ?

$$\begin{aligned}\theta &= \theta_0 [ 1 - \exp(-t/\tau)] \\ &= 100[ 1 - \exp(-1.5/3.5)] = 34.86^\circ\text{c}.\end{aligned}$$

38) A temperature-sensitive transducer is subjected to a sudden temperature change. It takes 10 s for the transducer to reach equilibrium condition (5 time constant). How long will it take for the transducer to read half of the temperature difference?

Time to reach equilibrium conditions =  $5\tau = 10\text{s}$ .

Time constant  $\tau = 10/5 = 2\text{s}$ .

$$\theta = \theta_0 [ 1 - \exp(-t/\tau)]$$

$$0.5 = 1 - [\exp(-t / 2)]$$

$$\therefore t = 1.39\text{s}.$$

### UNIT 3

44) What is potentiometer?

Basically a resistance potentiometer, or simply a POT, (a resistive potentiometer used for the purposes of voltage division is called a POT) consists of a resistive element provided with a sliding contact. The POT is a passive transducer.

45) What are the advantages and disadvantages of potentiometer?

Advantages :

- Inexpensive
- Useful for measurement of large amplitudes
- Efficiency is very high
- Frequency response of wire wound potentiometers is limited

Disadvantages :

- Require a large force to move

46) What is gauge factor?

The gauge factor is unit resistance change per unit strain, which is due to three factors as revealed by the above equation.

47) What are the different types of strain gauge?

- Unbonded metal strain gauges
- Bonded metal wire strain gauges
- Bonded metal foil strain gauges
- Vacuum deposited thin metal film strain gauges
- Sputter deposited thin metal strain gauges
- Bonded semiconductor strain gauges
- Diffused metal strain gauges.

48) What are the factors to be considered for bonded strain gauge?

- Filament construction
- Material of the filament wire
- Base carrier material or backing material
- Cement used to bond the filament to the carrier
- Lead wire connections.

49) What is strain?

It is a ratio of changing length to original length.

50) What is young's modulus ?

It is a ratio of stress and strain ,  $dR/R / dl/l$

51) What is resistance thermometers?

A resistance thermometer consists of a resistive element which is exposed to the temperature to be measured. If the conductors or metals are used to measure the temperature, they are known as resistance thermometers and if semiconductors are used then they are known as thermistors.

52) What are the different approximation methods of resistance thermometer?

- Linear approximation:
- Quadratic approximation

53) What is self heating error of thermometer?

Resistance thermometer bridges may be excited with either d.c. or a.c. The direct or rms alternating current through the thermometer is usually in the range of 2 to 20 mA. This current causes an  $I^2R$  heating which raises the temperature of the thermometer above its surroundings, causing the so-called self-heating error.

54) What are the advantages and disadvantages of resistance thermometers?

Advantages :

- They are suitable for measuring large temperature differences and high temperatures.
- They are very accurate which makes them suitable for small temperature measurement.
- Well designed resistance thermometers have excellent stability.
- Unlike thermocouples, they do not need a reference junction and this favors them in many aerospace and industrial applications.

Disadvantages :

- Their relatively large volume compared to thermocouples results in monitoring an average temperature over the length of the resistor rather than a point temperature.
- They need auxiliary apparatus and power supply.
- The resistance element is usually more expensive than a thermocouple.
- There are errors due to self heating and thermoelectric effect of the resistive element and connecting leads (dissimilar metal junctions).

55) What is the principle of hotwire anemometer?

Another resistance variation type transducer is hot wire anemometer. In general anemometers are devices used for measurement of velocity of flow.

56) Why dynamic compensation is required for hotwire anemometer?

It is used to avoid the fluctuation, we need dynamic compensation circuits for the hotwire anemometer.

57) What are the applications of thermistors?

- Measurement of power at high frequencies
- Measurement of thermal conductivity
- Measurement of level, flow and pressure of liquids

- Measurement of composition of gases
- Vacuum measurements
- Providing time delay.

58) Mention the features of thermistors.

- Compact, rugged and inexpensive.
- Good stability.
- The response time of thermistors can vary from a fraction of a second to minutes.
- Self heating of thermistors is avoided.
- Thermistors can be installed at a distance from their associated measuring circuits.

59) Mention the materials used for thermistors.

Mixture of metallic oxides such as manganese, nickel, cobalt, copper, iron and uranium.

60) Mention the applications of strain gauge.

- Used to measure pressure
- Used to measure torque
- Used to measure acceleration
- Used to measure force

## UNIT 4

61) What is inductance transducer?

Transducers based on the variation of inductance are another group of importance devices used in many application. In these transducers self inductance or the mutual of a couple of coils is changed when the quantity to be measured is varied.

62) Mention three principles of inductance transducer.

- Change of self inductance
- Change of mutual inductance
- Production of eddy currents.

63) What is LVDT?

The Linear Variable Differential Transformer (LVDT) is the most common mutual inductance element. This can be considered to be a versatile transducer element for most of the electromechanical measuring systems with regards to resolution, hysteresis, dynamic response, temperature characteristics, linearity and life.

64) What are the advantages and disadvantages of LVDT?

Advantages :

- High range
- Friction and electrical Isolation
- Immunity from external effects
- High input and high sensitivity
- Ruggedness
- Low hysteresis
- Low power consumption

Disadvantages :

- Relatively large displacements are required for appreciable differential output
- They are sensitive to stray magnetic fields but shielding is possible
- Many a times, the transducer performance is affected by vibrations.
- The receiving instrument must be selected to operate on a.c
- The dynamic response is limited
- Temperature affects the performance of the transducer.

65) What are the applications of LVDT?

- Displacement measurement and LVDT Gageheads
- LVDT pneumatic servofollower
- LVDT Loadcells
- LVDT Pressure Transducer

66) What is null voltage?

Ideally the output voltage at the null position should be equal to zero. However, in actual practice there exists a small voltage at the null position

67) Explain the principle of Induction Potentiometer?

The primary is excited with alternating current. This induces a voltage in the secondary. The amplitude of this output voltage varies with the mutual inductance between the two coils and this varies with the angle of rotation.

68) Explain the principle of Variable Reluctance Accelerometer?

Another common version of the variable reluctance principle. This is an accelerometer for measurement of acceleration in the range  $\pm 4g$ . Since the force required to accelerate a mass is proportional to the acceleration.

69) What is the need of demodulator in Variable Reluctance Accelerometer?

To detect motion on both sides of zero, a fairly involved phase-sensitive demodulator would be required. To eliminate the demodulator the iron core and springs were adjusted so that core was offset to one side by an amount equal to the spring deflection corresponding to 4 g acceleration.

70) What is the principle of capacitive transducer?

Many industrial variables like displacement, pressure, level, moisture, thickness etc can be transduced into an electrical variation using capacitance variation as the primary sensing principle.

71) What are the desirable features of capacitive transducer?

- Its force requirements are very small.
- As the moving plates have very little mass, design of transducer with fast response characteristics is possible.
- There is no physical contact between moving and stationary parts.
- Does not depend on the conductivity of the metal electrode.
- Shielded against the effect of external electric stray fields.

72) What are the different practical capacitance pickups?

- Equibar differential pressure transducer.
- Feedback type capacitance proximity pickup.
- Condenser microphone.

73) What is a Microphone?

It is also a transducer which converts sound energy into electrical energy. Example is condenser microphone.

74) What is the principle of change of capacitance?

- Change in overlapping area  $A$ ,
- Change in the distance between the plates,  $d$
- Change in dielectric constant.

75) What are the advantages of capacitive transducers?

- They require only small force to operate.
- Have a good frequency response.
- Extremely sensitive.
- High input impedance

76) What are the disadvantages of capacitive transducers?

- The metallic parts of the capacitive transducers must be insulated from each other.
- Non-linear behaviour
- This leads loading effects.
- The cable may be source of loading resulting loss of sensitivity.

77) What are the uses of capacitive transducer?

- Can be used for measurement of linear and angular displacement.
- Can be used for measurement of force and pressure.
- It can be used as pressure transducer.
- Measurement of humidity in gases.
- Commonly used for measurement of level, density, weight.

78) What is the value of capacitance for measurement of level of a non-conducting liquid?

$$C = 2\pi\epsilon_0 [\epsilon_1 h_1 + \epsilon_2 h_2 / \log_e (r_2/r_1) ]$$

where,  $h_1$  = height of liquid

$h_2$  = height of cylinder

$\epsilon_1$  = relative permittivity of liquid

$\epsilon_2$  = relative permittivity of vapour above liquid

$r_2$  = inside radius of outer cylinder

$r_1$  = outer radius of inner cylinder

$\epsilon_0$  = relative permittivity of free space

79) What is analog transducer?

These transducer convert input quantity into an analog output which is a continuous function of time. Thus a strain gauge, LVDT, thermocouple, thermistors, may be called as analog transducer.

80) What is digital transducer?

These transducer convert input quantity into an electrical output which is in the form of pulses.

## UNIT 5

81) What is piezo electric transducer?

They convert pressure or force into electrical charge. These transducers are based upon the natural phenomenon of certain non-metal and di-electric components.

82) What are the suitable materials for piezo electric transducer?

Primary quartz, Rochelle salt, ammonium dihydrogen phosphate (ADP), and ceramics with barium titanate, dipotassium tartrate, potassium dihydrogen phosphate and lithium sulfate.

83) What is '**d**' coefficient ?

Gives the charge output per unit force input (or charge density per unit pressure) under short circuit condition, it is measured in

Columbs / newton

84) What is '**g**' coefficient ?

g-coefficient representing the generated e.m.f gradient per unit pressure input.

$$\frac{V/m}{\text{Newton/m}^2}$$

85) What is '**h**' coefficient ?

It is obtained by multiplying the g-coefficient by young's modulus valid for the appropriate crystal orientation of the material, and thus measures the e.m.f gradient per unit mechanical deformation, or ( V/m ) / ( m/m )

86) What are the suitable materials for magnetostrictive transducer?

Iron , nickel, 68 permalloy, ferroxcube ect

87) What is magnetostrictive transducer?

The permeability can increase or decrease depending upon the material, type of stress , and the magnetic flux density in the sample.

88) What are the different magnetostrictive transducer?

- Magnetostrictive load cell
- Magnetostrictive Accelerometer
- Magnetostrictive Phonographic Pickup
- Magnetostrictive Torque Transducer

89) What are the errors in magnetostrictive transducer?

- Hysteresis
- Temperature
- Eddy current
- Input impedance

90) What are the special features of magnetostrictive transducer ?

- to measure large force
- measure several thousand “g”
- characteristics depend upon temperature.

91) What is fibre optic transducer?

Fibre optic cable consists of outer core and inner cladding. Data is transmitted in the form of light. It is used for measuring displacement, torsion.

92) Compare digital transducer with analog .

Digital transducer give digital outputs. Analog transducers outputs are continuous functions of time. If these analog transducers are to be interfaced with digital devices, then one has to use analog to digital converters.

93) How will u achieve high resolution in digital transducer?

The number of tracks must be increased and the length of each coded should be reduced, which would require fine brushes.

94) What are the different digital transducer are available?

- digital displacement transducer
- shaft angle encoder
- optical encoder
- magnetic encoder

95) what is piezo electric effect?

A piezo electric material is one in which an electric potential appears across certain surfaces of a crystal if the dimensions of the crystal are changed by the application of the mechanical force.

96) What id digitiser?

Digital encoding transducer or digitiser, enable a linear or rotary displacement to be directly converted into digital form without intermediate form of analog to digital (A/D) conversion.

97) What are the classifications of encoder?

- Tachometer transducer
- Incremental transducer
- Absolute transducer

98) What are the input characteristics of the transducer?

- Type of input and operating range
- Loading effect

99) What is zero error of the transducer?

In this case output deviates from the correct value by a constant factor over the entire range of transducer.

100) What are the different transfer characteristics of the transducer?

- Transfer function
- Error
  - ✓ Scale error
  - ✓ Zero error
  - ✓ Sensitivity error
  - ✓ Non- conformity
  - ✓ Hystereis
- Transducer response

\*\*\*\*\*

### TE unit 1

1) Ten measurements of pressure made by an instrument at different time intervals give the following readings in kg / cm<sup>2</sup> :

7.29, 8.03, 8.10, 7.95, 8.01, 7.98, 7.95, 8.07, 7.94 and 7.97.

find arithmetic mean, standard deviation, and most probable error.

**Answer : TRANSDUCER ENGINEERING – S.Renganathan** Page no-28;

2) Define standard. How are standards classified? . give the international standards used for mass, length, and time.

**Answer : TRANSDUCER ENGINEERING – S.Renganathan** Page no-22;

3) Discuss the various sources of errors in a measurement system. What is meant by error analysis? Why it is required? How is it done?

**Answer : TRANSDUCER ENGINEERING – S.Renganathan** Page no-6;

4) Explain ODD's and uncertainty.

**Answer : TRANSDUCER ENGINEERING – S.Renganathan** Page no-16;

### TE unit 2

1) List the static characteristics of measurement system and explain.

**Answer : TRANSDUCER ENGINEERING – S.Renganathan** Page no-46;

2) Derive the impulse response of the First Order System.

**Answer** **TRANSDUCER ENGINEERING – S.Renganathan** Page no-63;

3) Obtain the step response of a second- order system for different damping conditions.

**Answer :** **TRANSDUCER ENGINEERING – S.Renganathan** Page no-81;

4) A temperature transducer with a time constant of 0.4 sec and a static sensitivity of 0.05mV/ °c is used to measure the temperature of a hot liquid medium which changes from 25°C to 65°C. the transducer is adjusted to read 0 and 25°C.

(a) determine the time taken to read 80% of the final voltage value if the temperature changes as a step.

(b) Calculate the reading of the transducer at the end of 4 sec if the temperature changes at a constant rate of 10° per sec from 25°C to 65°C.

**Answer :** **TRANSDUCER ENGINEERING – S.Renganathan** Page no-105;

### **TE unit 3**

1) Give the materials, construction and installation details of bonded strain gauges. Give any two applications of bonded strain gauge.

**Answer :** **TRANSDUCER ENGINEERING – S.Renganathan** Page no-141;

2) Explain with a sketch the construction details and characteristics of a piezo resistive transducer.

**Answer :** **TRANSDUCER ENGINEERING – S.Renganathan** Page no-135;

3) Give the principle of operation, types and characteristics of potentiometer.

**Answer :** **TRANSDUCER ENGINEERING – S.Renganathan** Page no-117;

4) Give the principle of operation, construction and applications of thermistors.

**Answer :** **TRANSDUCER ENGINEERING – S.Renganathan** Page no-178;

### **TE unit 4**

1) Explain the principle, characteristics and advantages of LVDT.

**Answer :** **TRANSDUCER ENGINEERING – S.Renganathan** Page no-199;

2) Discuss the advantage and disadvantages and applications of capacitive transducer.

**Answer : TRANSDUCER ENGINEERING – S.Renganathan** Page no-227;

3) Explain with a sketch the principle of operation of a variable reluctance accelerometer.

**Answer : TRANSDUCER ENGINEERING – S.Renganathan** Page no-217;

4) Explain with a sketch the construction details, principle of operation and signal conditioning circuits of a capacitive transducer used for differential transducer.

**Answer : TRANSDUCER ENGINEERING – S.Renganathan** Page no-232;

### **TE unit 5**

1) Define the two sensitivity constants of piezo electric transducer. Derive the relation between the two constants. Also draw the equivalent circuit of piezo electric transducers.

**Answer : TRANSDUCER ENGINEERING – S.Renganathan** Page no-253;

2) Explain with the sketch the working of an encoder that gives 4 bit digital output proportional to linear displacement. Mention the advantages of digital transducer.

**Answer : TRANSDUCER ENGINEERING – S.Renganathan** Page no-284;

3) Define magnetostrictive effect. Name two materials used in magnetostrictive transducers. Describe any one application of magnetostrictive transducer.

**Answer : TRANSDUCER ENGINEERING – S.Renganathan** Page no-272;

4) Explain with a sketch the working of a fiber-optic displacement transducer. Draw its input – output characteristics .

**Answer : TRANSDUCER ENGINEERING – S.Renganathan** Page no-280;